

# Fuel Non-Availability Report

1. Vessel Name:	MV KATAGALAN WISDOM III
2. Vessel Flag:	PANAMA
3. IMO Number:	9599145

4. Ship's voyage plan in place at the time of entry into the North American ECA (alternatively, attach a copy of the vessel's Voyage Plan to this Report)

Ship's Voyage Plan attached: ☐ Voyage Information Below: ☒ X

(4.1) Port Information:

Port of Origin	IMMINGHAM, UK	Port of Destination	MOBILE, ALABAMA USA	The first U.S. Port	MOBILE, ALABAMA USA
----------------	---------------	---------------------	---------------------	---------------------	---------------------

(4.2) Vessel expect to Enter North American ECA:

Time:	18TH DECEMBER	Latitude:	25°57'24" N	Longitude:	79°41'01" W
-------	---------------	-----------	-------------	------------	-------------

(4.3) Vessel expects to exit North American ECA:

Time:	26TH DECEMBER	Latitude:	25°57'24" N	Longitude:	79°41'01" W
-------	---------------	-----------	-------------	------------	-------------

5. Type of Fuel that will be used when entering and operating in the North American ECA

Oil Type:	HSFO LSMGO	Sulfur content:	3% (3.5% MAX) <1% (1% MAX)	Estimated Usage Quantity:	~50 MT ~30 MT
-----------	---------------	-----------------	-------------------------------	------------------------------	------------------

6. Description of the actions taken to attempt to achieve compliance prior to entering the North American ECA:

A description of the actions taken to attempt to achieve compliance prior to entering the North American ECA, including a description of all attempts that were made to locate alternative sources of compliant fuel oil, and a description of the reason why compliant fuel oil was not available (e.g., compliant fuel oil was not available at ports on "intended voyage," fuel oil supply disruptions at port, etc.

IMMINGHAM TO CALL AT USA PORT/S

IT WAS NOT INTENDED WHEN LEAVING

In cases of fuel oil supply disruption, the name of the port at which the vessel was scheduled to receive compliant fuel oil and the name of the fuel oil supplier that is now reporting the non-availability of compliant fuel oil

(6.1) Attempts were made to obtain compliant fuel in the following ports on the vessel's voyage. A list of these ports and suppliers is below.

(6.2) Compliant fuel oil was not available at the following ports during the vessels "intended voyage":

1. WHEN VESSEL WAS DIVERTED FROM BALLAST VOYAGE TO VENEZUELA (POSN 20°49' N 4°52'29" W) THERE WERE NO SUITABLE BUNKERING STATIONS EN ROUTE.

2.

3.

Etc,

(6.3) Suppliers names and addresses contact was made:

Number	Supplier Name:	Suppliers Address	Phone Number	Email	Date
1.	SHELL MARINE	FREEPORT, BAHAMAS	+1 713 230 4058	GXTRShellAmericasBunkerSales@shell.com	11TH DECEMBER 2014
Reason fuel not available: CHANGEOVER					
2.					
Reason fuel not available:					
3.					
Reason fuel not available:					
4.					
Reason fuel not available:					
5.					
Reason fuel not available:					
6.					
Reason fuel not available:					
7.					
Reason fuel not available:					
8.					
Reason fuel not available:					
9.					
Reason fuel not available:					
10.					
Reason fuel not available:					

**7. Vessel is scheduled to receive compliant fuel Oil:**

*The availability of compliant fuel oil at the first port-of-call in the United States, and your plans to obtain that fuel oil. If compliant fuel oil is not available at the first port-of-call in the United States, the lowest sulfur content of available fuel oil, or the lowest sulfur content of available fuel oil at the next port-of-call in the United States*

(7.1) First port-of-call in the United States

Port Name:	MOBILE, AL	Supplier:	PHYSICAL SUPPLIERS VIA GLOBAL VISION BUNKERS
------------	------------	-----------	--



I certify under penalty of law that the statements and information made herein are, to the best of my knowledge and belief, true and complete. I am aware that there are significant penalties for knowingly submitting false statements and information, including the possibility of fines and imprisonment pursuant to 18 U.S.C. § 1001.

Master:

Chief Engineer:

Ashley Global Shipping Ltd

9. Company and Ship's Agent contact information:

Company Name	Address	Telephone
ASHLEY GLOBAL SHIPPING LIMITED	122 TOOLEY STREET LONDON	+442074034908
	SE1 2TU	
Ship's Agent in the US	Address	Telephone
T. PARKER HOST INC.	200 SOUTH ROYAL STREET MOBILE, AL	251 433 1536

10. Submit bmit Fuel Oil Non-Availability Report to the United States government to the following no later than 96 hours prior to entering the North American ECA.

Entity:

Email or Fax Number

US Government:

[Marine-eca@epa.gov](mailto:Marine-eca@epa.gov)

Company:

Flag Administration